



# DIMENSÕES / DIMENSIONS / DIMENSIONES

## TABELA DE MEDIDAS / MEASURES CHART / TABLA DE MEDIDAS

### VBW




### VBA



A	ALTURA/HEIGHT	10	12	13	14	15	16	18	20	22	25	30
	TRILUX		X		X		X	X	X		X	
	MONOCOLOR		X		X	X	X	X	X	X	X	X
	BURNOUT/CALCINABLE	X	X		X	X	X	X	X	X	X	
	WAX	X	X		X		X	X	X		X	X


A	ALTURA/HEIGHT	10	12	13	14	15	16	18	20	22	25	30
	TRILUX			X					X		X	
	MONOCOLOR			X					X		X	
	BURNOUT/CALCINABLE			X					X		X	
	WAX			X				X	X			

### VBD



A	ALTURA/HEIGHT	10	12	13	14	15	16	18	20	22	25	30
	TRILUX				X		X		X	X		
	MONOCOLOR				X		X		X	X		
	BURNOUT/CALCINABLE				X		X		X	X		
	WAX		X		X		X	X	X	X		


### VBS



A	ALTURA/HEIGHT	16
	TRILUX	X
	MONOCOLOR	X
	BURNOUT/CALCINABLE	X


# MEDIDAS EM mm / MEASURES IN mm / MEDIDAS EN mm

## VBZ




A	ALTURA/HEIGHT	10	12	13	14	15	16	18	20	22	25	30
	TRILUX		X				X		X		X	
	MONOCOLOR		X				X		X		X	
	BURNOUT/CALCINABLE		X				X		X		X	
	WAX	X	X		X		X	X	X		X	X

## VBC




A	ALTURA/HEIGHT	10	12	13	14	15	16	18	20	22	25	30
	TRILUX		X		X		X	X	X			
	MONOCOLOR						X	X	X	X	X	
	BURNOUT/CALCINABLE							X	X	X		
	WAX		X				X	X	X	X		

## VBR



A	ALTURA/HEIGHT	10	12	13	14	15	16	18	20	22	25	30
	TRILUX						X		X			
	MONOCOLOR						X		X			
	BURNOUT/CALCINABLE						X		X			
	WAX						X		X			

## VBRH



A	ALTURA/HEIGHT	10	12	13	14	15	16	18	20	22	25	30
	TRILUX						X		X			
	MONOCOLOR						X		X			
	BURNOUT/CALCINABLE						X		X			
	WAX						X		X			